

## NEW FEATURES

This is a service pack release for FieldGenius to add support for new survey instruments and fix high priority defects.

## NEW AND UPDATED INSTRUMENT DRIVERS

### GNSS

- CY F100 – Added New Driver.
- Hemisphere S631 GNSS - Added New Driver.
- Tersus GNSS Devices – Updated reference distance for GNSS.
- GENEQ F100 – Updated Driver.
- Leica Devices - Add support for Satel 900MHz Radio.
- Tersus - Add support for GSA and GSV messages.
- Stonex - Add S990A and S980 - Added New Driver.
- KOLIDA K1PRO and K20s - Added New Drivers.
- CHC i80 – Updated driver to support new firmware version.

### Total Station

- CHC CTS-112R4 - Added New Driver.

### Coordinate Systems

- [FEA3979] POSGAR 94 and 2007 for Argentina

## DEFECTS FIXED

- Observation Toolbar – Fixed bug when switching to staking mode.
- Changing GNSS Tolerance – Fixed wait dialog does not close issue.
- eSurvey E100 – Updated driver to address GSM issue.

## KNOWN ISSUES

**Tersus Oscar** – Setting Oscar as Reference Station provides incorrect height. (Contact MicroSurvey or Tersus for the solution)

**Disto S910** - First photo taken with project can provide an error, additional photos are taken and stored fine.

**Photo Notes** – Camera rotation is not supported.

**LandXML** – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

**Multiset Structured** – Angle only backsight is not available.